



PDH-Pro.com

## Welding Safety

**Course Number:** HS-02-301

**PDH:** 3

**Approved for:** AK, AL, AR, DE, FL, GA, IA, ID, IL, IN, KS, KY, LA, MD, ME, MI, MN, MO, MS, MT, NC, ND, NE, NH, NJ, NM, NV, NY, OH, OK, OR, PA, SC, SD, TN, TX, UT, VA, VT, WI, WV, and WY

### State Board Approvals

Florida Provider # 0009553 License #868

Indiana Continuing Education Provider #CE21800088

Maryland Approved Provider of Continuing Professional Competency

New Jersey Professional Competency Approval #24GP00025600

North Carolina Approved Sponsor #S-0695

NYSED Sponsor #274

### How Our Written Courses Work

This document is the course text. You may review this material at your leisure before or after you purchase the course.

After the course has been purchased, review the technical material and then complete the quiz at your convenience.

A Certificate of Completion is available once you pass the exam (70% or greater).

If a passing grade is not obtained, you may take the quiz as many times as necessary until a passing grade is obtained).

If you have any questions or technical difficulties, please call (508) 298-4787 or email us at [admin@PDH Pro.com](mailto:admin@PDH Pro.com).





## Module 1: Welding, Cutting, and Compressed Gas Cylinder Safety

### Learning Objectives

By the end of this section, you will be able to:

- **Evaluate** job site storage and handling procedures for compressed gas cylinders to ensure compliance with DOT and OSHA standards.
- **Identify** and **mitigate** chemical and physical health hazards associated with specific base metals and welding processes.
- **Select** appropriate mechanical ventilation or respiratory protection based on the toxicity of materials and the work environment.

*Executive Summary:* Safe welding and cutting operations require the rigorous management of high-pressure gas cylinders, the maintenance of electrical integrity in arc equipment, and the implementation of specific ventilation controls to protect against toxic metal fumes and harmful radiation.

### Gas Welding and Cutting Fundamentals

#### Handling and Moving Compressed Gas Cylinders

Proper handling is critical to prevent accidental discharge or physical injury. **Valve protection caps** must remain in place and be securely tightened whenever cylinders are not in use or are being moved.

- **Hoisting Operations:** Secure cylinders on a **cradle, slingboard, or pallet**. Never use magnets or choker slings for hoisting.
- **Manual Movement:** Move cylinders by **tilting and rolling** them on their bottom edges. Do not drop or allow them to strike each other.
- **Vehicle Transport:** Secure all cylinders in a **vertical position** when using powered vehicles.
- **Frozen Cylinders:** Use **warm water** (not boiling) to thaw frozen cylinders. Never pry them loose with bars under the valves.

#### Cylinder Storage and Placement

Storage areas must be designed to isolate fuel gases from oxidizers and protect the vessels from external damage.

- **Separation Requirements:** Store **oxygen cylinders** at least **20 feet** (6.1 m) away from fuel-gas cylinders or combustible materials. Alternatively, use a **noncombustible barrier** at least 5 feet (1.5 m) high with a minimum **0.5-hour fire-resistance rating**.



- **Location Constraints:** Store cylinders in well-ventilated, dry areas away from elevators, stairs, or gangways where they could be struck.
- **Operational Placement:** Keep cylinders far enough from the arc or flame to prevent contact with sparks or hot slag; use **fire-resistant shields** if distance is insufficient.

⚠ **Safety Constraint:** Fuel gas cylinders must be placed with the **valve end up** whenever they are in use.

### Fuel Gas Usage and Equipment Safety

- **Cracking the Valve:** Before connecting a regulator, open the valve slightly and close it immediately to clear dust. Stand to the side of the outlet, never in front of it.
- **Opening Procedures:** Open valves **slowly**. For quick closing, do not open fuel gas valves more than **1.5 turns**.
- **Manifolds:** Manifold hose connections must be designed so they are **not interchangeable** between fuel gas and oxygen. **Adapters** are prohibited for interchanging hoses.

### Arc Welding and Cutting

#### Manual Holders and Cables

- **Insulation:** All current-carrying parts of the holder gripped by the welder, including the outer jaws, must be **fully insulated**.
- **Cable Integrity:** Use only flexible, completely insulated cables. Cables must be free from repair or splices for at least **10 feet** from the electrode holder.

#### Grounding and Machine Safety

- **Ground Returns:** The return cable must have a current-carrying capacity equal to or exceeding the unit's maximum output.
- **Prohibited Grounds:** Never use pipelines containing gases/flammable liquids or conduits with electrical circuits as a ground return.
- **Machine Grounding:** Ground the frames of all machines through a **third wire** in the cable or a separate wire grounded at the source.

#### Fire Prevention and Mitigation

- **Movable Hazards:** Move movable fire hazards to a safe location or provide positive confinement for heat and sparks if the object cannot be moved.




- **Extinguishers:** Suitable equipment must be **immediately available** and ready for instant use.
- **Confined Spaces:** When working in enclosed spaces, the gas supply to the torch must be **shut off outside** the space whenever the torch is left unattended.

## Ventilation and Health Hazard Management

### Mechanical Ventilation Requirements


Ventilation is deemed adequate if it keeps contaminant concentrations in the breathing zone within safe limits.

| Context                               | Requirement   |
|---------------------------------------|---|
| Confined Spaces                       | Mechanical ventilation is mandatory unless airline respirators are used.              |
| Beryllium Work                        | Requires both local exhaust ventilation and airline respirators due to high toxicity. |
| Toxic Metals (Lead, Cadmium, Mercury) | Requires local exhaust ventilation or airline respirators in enclosed spaces.         |

 **Safety Constraint: Oxygen** must never be used for ventilation, comfort cooling, or cleaning dust from clothing.

### Chemical and Physical Hazards

- **Zinc (Galvanized):** Exposure causes **metal fume fever**, with influenza-like symptoms typically lasting less than 24 hours.
- **Lead:** Inhalation of lead oxide fumes from paint or alloys causes poisoning, affecting the **central nervous system** and kidneys.
- **Ultraviolet (UV) Radiation:** Produced by the electric arc, UV can cause **severe skin burns** and "arc-eye" (retinal damage).
- **Phosgene Gas:** Formed when UV radiation decomposes **chlorinated hydrocarbon solvent** vapors; it is highly toxic and destroys lung tissue.

 **Design Tip:** When welding stainless steel using inert-gas metal-arc processes, prioritize local exhaust to protect against **nitrogen dioxide** concentrations.



---

*Checkpoint Quiz*

---

**1. When transporting compressed gas cylinders via a powered vehicle, what is the required orientation?**

- a) Horizontal, secured with chocks.
- b) Vertical and secured.
- c) Tilted at a 45-degree angle.
- d) Any orientation is acceptable if the valve cap is on.

**Answer: (b).** Cylinders must be secured in a vertical position during vehicle transport.

**2. According to safety standards, how far must oxygen cylinders in storage be separated from fuel-gas cylinders if a fire-resistant barrier is not used?**

- a) 5 feet
- b) 10 feet
- c) 20 feet
- d) 50 feet

**Answer: (c).** A minimum distance of 20 feet (6.1 m) is required for separation.

**3. Which condition is specifically associated with the inhalation of zinc oxide fumes during the welding of galvanized metals?**

- a) Phosgene poisoning
- b) Metal fume fever
- c) Arc-eye
- d) Silicosis

**Answer: (b).** Zinc oxide fumes are known to cause metal fume fever, which presents with flu-like symptoms.



Purchase this course to  
see the remainder of  
the technical materials.